Official copies of these procedures are maintained at this website.

Before using a printed copy, verify that it is the most current version by checking the document issue date on this website. Signed copies of these official procedures are maintained at the Training Office.

C-A OPERATIONS PROCEDURES MANUAL

ATTACHMENT

4.56.z V Target Station Sweep Checklist

Text pages 2 through 3

	C-A OPM Proced	lures in which this At	tachment is used.	
	4.56			
	<u>Ha</u>	and Processed Change	es	
HPC No.	<u>Date</u>	Page N	Nos. <u>In</u>	<u>itials</u>
				Revision No. 00
		:Signa Collider-Accelerator I		

ONCE A SWEEP IS COMPLET IF any personnel are encountered of completed in a short time. IF the workshould be aborted or the workers a completed in a SHORT time, THEN	Operator 2Date: Warning: TE, ANY WORKER LEFT IN THE ENCLOSURE MUST HAVE A CA(EB006) KEY.
ONCE A SWEEP IS COMPLET IF any personnel are encountered of completed in a short time. IF the workshould be aborted or the workers a completed in a SHORT time, THEN	Warning: TE, ANY WORKER LEFT IN THE ENCLOSURE MUST
IF any personnel are encountered of completed in a short time. IF the workshould be aborted or the workers a completed in a SHORT time, THEN	TE, ANY WORKER LEFT IN THE ENCLOSURE MUST
IF any personnel are encountered of completed in a short time. IF the workshould be aborted or the workers a completed in a SHORT time, THEN	,
completed in a short time. IF the work should be aborted or the workers a completed in a SHORT time, THEN	
	during the sweep, THEN determine whether their work will be k will take a long time, THEN contact the OC to see if the sweep asked to leave to obtain a CA(EB006) key. IF the work will be N write the name(s) of the workers at the end of the checklist and leave the enclosure WITH the sweep team.
 C Required Tools: at least one flas C Personal TLD and self-reading C Walkie-talkie 	klist for C-A-OPM-ATT 4.56.z (one sheet)
Contamination Workers. Ask	Warning: ntamination Area. Sweeps shall be conducted by trained HP if contamination is present and whether Contamination rea Procedure is to be followed.
This procedure is the ONLY reset stati	Warning:

Team Leader contacts MCR to verify that Uup/V_target is on Controlled Access. ____2. Sweep Team goes to the gate VPGE1 Team Leader requests Simultaneous Release from operator in MCR sweep team enters

C-A-OPM-ATT 4.56.z (Y)

check

Revision 00

usi 4.	ng the CA(EB005) key in the OPEN key-switch. Sweep Team proceeds to VTGE1.			
CONTINUED ON REVERSE SIDE				
5.	Team Leader determines whether the V Target shutter is closed. IF the shutter is NOT closed THEN contact the CAS watch to come to VTGE1 and close it. (Ask CAS to remain at the gate to open the shutter at the end of the sweep).			
When tl	Note: ne V Target Shutter is closed, contact Health Physics to determine the residual levels outside the shutter.			
6.	If VTGE1 is padlocked then go to Step 16.			
7.	Team Leader requests simultaneous release from MCR for VTGE1.			
8.	Team leader opens VTGE1 gate by turning the S/R(EB007) key in the OPEN key-switch while			
	Operator in MCR holds the gate release.			
9.	Team Leader stands static watch outside VTGE1.			
10.	Operator #2 passes through VTGE1.			
11.	Operator #2 proceeds to the upstream end of the cave at VQ12.			
12.	Operator #2 sweeps upstream to check station at the end of cave.			
13.	Operator #2 sweeps downstream past the V target station shutter.			
14.	Operator #2 sweeps out VTGE1.			
15.	Team Leader closes VTGE1.			
16.	Team Leader starts Sweep by pushing red push button on underside of gate box outside			
	VTGE1. Observe Area Secured lamp blink once.			
17.	Team Leader ends the sweep by resetting the sweep zone at the gate box outside and left of			
	VTGE1 by turning the S/R(EB007) key in the RESET key-switch.			
18.	Observe the AREA SECURED amber light remains lit.			
19.	Team Leader resets gate VTGE1 by turning the S/R(EB007) key in the RESET key-switch.			
20.	Observe the GATE RESET amber light will remain lit.			
21.	Team Leader confirms with an operator in the MCR that the gate is reset and that the sweep is			
25	OK.			
22.	Team Leader notifies CAS that target shutter may be opened.			
23.	Team Leader notifies CAS to install the padlock on VTGE.			
24.	Team Leader files completed checklist in FY`nn Sweep Log binder.			